


1970-1972 R50/5 — R75/5 (without Fuses)



blue/black

Front Turn Signal

Indicator Warming Light

COMPLETE HEADLIGHT ASSEMBLY

CONNECTORS

OFF-NO CONNECTIONS

56b.

31

56a

Late 1972-1973 R50/5 — R75/5 (with Fuses)

